

EXHIBIT B

Overdue Lead Paint Violations (5)

S.No.	VIOLATION ID	CLASS	ORDER #	APT #	STORY #
1	12774620	C	616	4	3
	REPORTED DATE	NOV ISSUED DATE	NOV ID	NOV TYPE	CORRECTION BY DATE
	11/27/2018	11/28/2018	0	-	-
	CERTIFICATION BY DATE	VIOLATION STATUS	VIOLATION STATUS DATE	ACTUAL CERT. DATE	VIOLATION DESCRIPTION
	-	-	-	-	-

VIOLATION DESCRIPTION

§ 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY §11-06(B)(2) NORTH WALL IN THE 3rd ROOM FROM NORTH AT WEST LOCATED AT APT 4, 3rd STORY, 1st APARTMENT FROM NORTH AT EAST

S.No.	VIOLATION ID	CLASS	ORDER #	APT #	STORY #
2	12774619	C	616	4	3
	REPORTED DATE	NOV ISSUED DATE	NOV ID	NOV TYPE	CORRECTION BY DATE
	11/27/2018	11/28/2018	0	-	-
	CERTIFICATION BY DATE	VIOLATION STATUS	VIOLATION STATUS DATE	ACTUAL CERT. DATE	VIOLATION DESCRIPTION
	-	-	-	-	-

VIOLATION DESCRIPTION

§ 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY §11-06(B)(2) WEST WALL IN THE 2nd BATHROOM FROM NORTH AT WEST LOCATED AT APT 4, 3rd STORY, 1st APARTMENT FROM NORTH AT EAST

S.No.	VIOLATION ID	CLASS	ORDER #	APT #	STORY #
3	12774618	C	616	4	3
	REPORTED DATE	NOV ISSUED DATE	NOV ID	NOV TYPE	CORRECTION BY DATE
	11/27/2018	11/28/2018	0	-	-
	CERTIFICATION BY DATE	VIOLATION STATUS	VIOLATION STATUS DATE	ACTUAL CERT. DATE	VIOLATION DESCRIPTION
	-	-	-	-	-

VIOLATION DESCRIPTION

§ 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY §11-06(B)(2) SOUTH WALL IN THE 1st ROOM FROM NORTH AT EAST LOCATED AT APT 4, 3rd STORY, 1st APARTMENT FROM NORTH AT EAST

S.No.	VIOLATION ID	CLASS	ORDER #	APT #	STORY #
4	12774617	C	616	4	3
	REPORTED DATE	NOV ISSUED DATE	NOV ID	NOV TYPE	CORRECTION BY DATE
	11/27/2018	11/28/2018	0	-	-
	CERTIFICATION BY DATE	VIOLATION STATUS	VIOLATION STATUS DATE	ACTUAL CERT. DATE	VIOLATION DESCRIPTION
	-	-	-	-	-

VIOLATION DESCRIPTION

§ 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY §11-06(B)(2) NORTH WALL IN THE 3rd ROOM FROM NORTH AT EAST LOCATED AT APT 4, 3rd STORY, 1st APARTMENT FROM NORTH AT EAST

S.No.	VIOLATION ID	CLASS	ORDER #	APT #	STORY #
5	12774616	C	616	4	3

REPORTED DATE	NOV ISSUED DATE	NOV ID	NOV TYPE	CORRECTION BY DATE
---------------	-----------------	--------	----------	--------------------

11/27/2018	11/28/2018	0	-	-
------------	------------	---	---	---

CERTIFICATION BY DATE	VIOLATION STATUS	VIOLATION STATUS DATE	ACTUAL CERT. DATE	VIOLATION DESCRIPTION
-----------------------	------------------	-----------------------	-------------------	-----------------------

-	-	-	-	-
---	---	---	---	---

VIOLATION DESCRIPTION

§ 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY §11-06(B)(2) SOUTH WALL IN THE 1st KITCHENETTE FROM NORTH AT WEST LOCATED AT APT 4, 3rd STORY, 1st APARTMENT FROM NORTH AT EAST